



Regn No 73/2005-06

Kendriya Vihar-II Apartment Owners' Association
Community Centre-1, Kendriya Vihar-II, Plot No.3, Sector-82, Noida-201304, U.P.
(website: www.noidakv2.org ; E-mail: noidakv2@gmail.com ; Tel: 0120-4984693)

KV-II/Admin/2024-2025/127

Dated: 15.06.2024

To,
The SHO
Phase-II, Police Station Noida
Gautam Budh Nagar
Uttar Pradesh-201304

Subject: Information with regard to missing Items of Kendriya Vihar-II, Sector-82 Noida

Sir,

Please refer to our letter no. KV-II/Admin/2023-2024/118 dated 31.08.2023 on the subject mentioned above. We are required to brief our General Body on this matter, in its forthcoming meeting. You are therefore requested to let us know the action taken on the letter under reference so far.

The Board of Management of the society would be happy to provide any assistance required for investigating the matter.

Thanking You


Yours Faithfully

R. Sharma 15/6/24
(Ramesh Sharma)
Secretary, AOA

Encl: Copy of letter no. KV-II/Admin/2023-2024/118 dated 31.08.2023

Copy to:

1. Copy to ACP, Phase-II, Gautam Budh Nagar
2. Copy to PS to commissioner of Police, Gautam Budh Nagar





Kendriya Vihar-II Apartment Owners' Association
Community Centre-1, Kendriya Vihar-II, Plot No.3, Sector-82, Noida-201304, U.P.
(website: www.noidakv2.org ; E-mail: noidakv2@gmail.com ; Tel: 0120-2463700)

KV-II/Admin/2023-2024/118

Dated: 31.08.2023

To,

The SHO
Phase-II, Police Station Noida
Gautam Budh Nagar
Uttar Pradesh -201304

Subject: Information with regard to the missing items of Kendriya Vihar-II, Sector-82, Noida

Sir,

The Fire Hydrant System of the society had been a matter of concern for the concerned authorities and the society had been penalised for not having the desired level of systems in place. The new Board of Management of AOA, Kendriya Vihar-II, Sector-82, Noida took over on 27th February 2023. On taking over the charge, the new management started working on filling the gap between the systems expected to be in place and the systems actually in place. For this a physical verification of the Fire Hydrant Systems installed in the society and the systems physically available on ground was carried out. This physical verification threw light on number of items missing. Details of these missing items are given in Annexure -1.

Further, special audit of this society has been ordered by the office of Deputy Registrar of Societies. During the course of audit, some of the documents demanded by the auditor were found missing. List of the documents which were found missing, is given in Annexure-2

The information is provided to you for further necessary action.

Thanking You

President, may kindly approve before issue.

Yours Faithfully

[Signature]
(Dr. Lokesh Kumar Sinha)
(Secretary, AOA)

Copy to:-

1. ACP Phase-II Goutambudh Nagar
2. PS to Commissioner Police, Goutambudh Nagar

President

[Signature]
2/9/23

FIRE HYDRANT SYSTEM (In 120 Blocks)

	PRESSURE GAUGE	LANDING VALVE BODY	HOSE REEL DRUM	HOSE REEL TUBE	HOSE NOZZEL	HOSE BOX GLASS	AIR VENT	BOOSTER PUMP	PUMP PANEL
Missing	694	487	1	5	744	274	104	Nil	Nil
Available	50	257	743	740	Nil	470	7	24	24

Note: All Brass Nozzles fitted on Hose Reel Tube (740 in numbers) are missing

FIRE HYDRANT SYSTEM (In Open Area)

	HYDRANT POINT	CONTROL VALVE	CONTROL VALVE BODY	BRASS HOSE NOZZLES	HOSE PIPES	HOSE BOX
Missing	01	101	28	101	101	48
Available	100	Nil	73	Nil	Nil	53

LIST OF MISSING DOCUMENTS

PAN CARD OF AOA - Pan No AAAAK5568N

CHEQUE PAYMENT VOUCHER FILE MONTH OF OCTOBER 2018

AIR CONDITIONER BILLS OF Rs. 72000 DATED 04-06-2014

FURNITURE & FITTING BILL DATED 27-04-2014 Rs.99540

ALL RELATED PAPER AND PAYMENT VOUCHER OF
CCTV CAMERA INSTALLATION IN KV-II